



Report Number: TOPDON1779917313

SN: 110499X5C20388

Date Created: 2026-05-27

TOPDON ID: U2D5JIH7C9

Chevrolet Truck-4x2, ton Chevrolet Suburban LT-2012_Fault Code Report

Plate Number:	Make:Chevrolet Truck
Model:4x2, ton Chevrolet Suburban LT	Year:2012
Distance Traveled:	Engine:
Sub Model:	Diagnostic Time:2026-05-27 16:28:33
Vehicle Software Version:V3.30	Diagnostic Application Version:V6.35.300
VIN:1GNSCJE00CR128969	Diagnostic Scan Path:660006000001/Light duty truck, MPV, Incomplete/Chevrolet Truck/4x2, ton Chevrolet Suburban LT/ Under 8600 GVW/Without (RPO Z95)/ Without trailer brake/Automatic HVAC/ Navigation radio/Engine control module
Customer:	Phone Number of Customer:
Ticket No.:	

Fault Code Report (19)

Engine control module

DTC	Description	Status
P162B:00	Remote vehicle speed limiting signal circuit	Last test: Not run This ignition: Not run Since DTC cleared: Not run
P3400:00	Cylinder deactivation system	Last test: Not run This ignition: Not run Since DTC cleared: Not run
P3401:00	Cylinder 1 deactivation solenoid control circuit	Last test: Not run This ignition: Not run Since DTC cleared: Not run

P3425:00	Cylinder 4 deactivation solenoid control circuit	Last test: Not run This ignition: Not run Since DTC cleared: Not run
P3441:00	Cylinder 6 deactivation solenoid control circuit	Last test: Not run This ignition: Not run Since DTC cleared: Not run
P3449:00	Cylinder 7 deactivation solenoid control circuit	Last test: Not run This ignition: Not run Since DTC cleared: Not run
P0053:00	Heated Oxygen Sensor (HO2S) heater resistance (bank 1 sensor 1)	Not run
P0054:00	Heated Oxygen Sensor (HO2S) heater resistance (bank 1 sensor 2)	Not run
P0059:00	Heated Oxygen Sensor (HO2S) heater resistance (bank 2 sensor 1)	Not run
P0060:00	Heated Oxygen Sensor (HO2S) heater resistance (bank 2 sensor 2)	Not run
P0116:00	Engine Coolant Temperature (ECT) sensor performance	Not run
P0442:00	Evaporative Emission (EVAP) system small leak detected	Not run
P0446:00	Evaporative Emission (EVAP) vent system performance	Not run
P0451:00	Fuel Tank Pressure (FTP) sensor performance	Not run
P0454:00	Fuel Tank Pressure (FTP) sensor circuit intermittent	Not run
P0455:00	Evaporative Emission (EVAP) system large leak detected	Not run
P0464:00	Fuel level sensor circuit intermittent	Not run
P0496:00	Evaporative Emission (EVAP) system flow during non-purge	Not run

Disclaimer

This diagnostic report is provided for the purpose of displaying diagnostic data and is for reference only. It does not constitute any judgment, conclusion, or basis for action. The Company shall not be liable for any decisions or actions taken by the user based on the content of this report.

When a user chooses to save the diagnostic report to the App client, the relevant report content will be stored in accordance with the App’s functional requirements for the purpose of subsequent access.