

The clock in our 2007 GMC Yukon XL Denali suddenly displayed no time, just the ‘.’ Attempting the adjust time in the normal manner did nothing but beep with pressing the adjust time keys. I have documented the step I used to get the clock back into operation. I must give credit to a May 2008 posting by “2007TahoeLTZ4x\$” found in “Tahoe Forum.com”. I followed his instructions and the worked. I only took new pictures during my process.




Press in lower left corner of screen for five seconds until keypad displays




Enter code 295660, another reported code is 9448 that is supposedly a more extensive version of 295660.




Press OK Button After PIN Entered



Press Next Page






Note that nothing is showing in the columns. Press the buttons to set date and time. Once set to GMT time the clock should display your own timezone after exiting this setup procedure.



Press the Set button when all data is entered and then press the Back button.



Time is displayed!!

