

#PIT5949: Overhead Roof Console Inoperative / Service Safety Restraints Message / Sunroof Inoperative / Dome Lights Inoperative / DTCs B1A7A and U1121 - (Sep 27, 2022)

Subject: Overhead Roof Console Inoperative / Service Safety Restraints Message / Sunroof Inoperative / Dome Lights Inoperative / DTCs B1A7A and U1121



Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2021-2023		All	All	All	All
Chevrolet	Suburban	2021-2023		All	All	All	All
Chevrolet	Tahoe	2021-2023		All	All	All	All
GMC	Yukon Models	2021-2023		All	All	All	All

Involved Region or Country	North America
Condition	In some rare cases, a customer may comment at start up that their vehicle has the following symptoms: - Service Safety Restraints System Message - Sunroof Inoperative - Sunshade Lights Inoperative - Dome Lights Inoperative - Power Liftgate Inoperative when using switch in overhead console - DTCs U1121 set in the BCM and B1A7A set in the Restraints Module During the condition, if one of the overhead roof console dome/map lights is cycled on/off then all functions will return to normal operation for the entire ignition cycle. Important: Even when all other overhead roof console functions are inoperative, the Onstar button / LED will still be operational.

© 2022 General Motors. All rights reserved.

	Note: For the 2021 model year vehicles, please be aware of PIT5774F which has a similar condition, but the conditions listed in that PI do not recover functionality if the dome/map light switch is cycled on/off.
Cause	Unknown

Correction

GM Engineering is working on a fix. In the meantime, if this condition occurs please ask the customer to cycle one of the overhead roof console dome/map lights on/off. This will correct the concerns for that ignition cycle.

Version	1
Modified	09/27/2022 – Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION