



PROFESSIONAL REPORT

● Passenger Door Switch (PDS)



Version Information

DTC Qty (14)

U0155-00	Lost Communication with Instrument Panel Cluster (IPC)
U0164-00	Lost Communication with Heating Ventilation Air-conditioning And Cooling (HVAC) Control Module
U0156-00	Lost Communication with Information Center A
B1023-00	Integral Switch Malfunction
B1600-02	Mirror Motor Vertical Circuit Short to Ground
B3205-0B	Driver Window Motor Circuit
B3205-00	Driver Window Motor Circuit Malfunction
B2555-02	Passenger Compartment Lamp Control Circuit Short to Ground



Report



B2555-02	Passenger Compartment Lamp Control Circuit Short to Ground
B2555-01	Passenger Compartment Lamp Control Circuit Short to Battery
U0140-00	Lost Communication with Body Control Module
U0199-00	Lost Communication with Door Control Module A
U0208-00	Lost Communication with Seat Control Module A
B1000-34	Electronic Control Unit (ECU) Performance Checksum Error
B1000-43	Electronic Control Unit (ECU) Performance EEPROM Error

Live data Qty (0)

● Electronic Suspension Control (ESC)



Version Information

DTC Qty (1)

C0660-06	Level Control Exhaust Valve Circuit Short to Ground or Open Circuit
----------	---



● Electronic Suspension Control (ESC)



Version Information

DTC Qty (1)

C0660-06	Level Control Exhaust Valve Circuit Short to Ground or Open Circuit
----------	---

Live data Qty (0)

● Rollover Sensor (RS)



Version Information

DTC Qty (1)

B1011-71	System Disabled Information Stored Invalid Serial Data Received
----------	---

Live data Qty (0)

● Supplemental Inflatable Restraint (SIR)



Version Information

DTC Qty (8)