



● Driver Door Switch (DDS)



Version Information

DTC Qty (8)

U0155-00	Lost Communication with Instrument Panel Cluster (IPC)
B3205-0B	Driver Window Motor Circuit
B3205-00	Driver Window Motor Circuit Malfunction
B2555-02	Passenger Compartment Lamp Control Circuit Short to Ground
B2555-01	Passenger Compartment Lamp Control Circuit Short to Battery
U0140-00	Lost Communication with Body Control Module
B1000-43	Electronic Control Unit (ECU) Performance EEPROM Error
B1000-35	Electronic Control Unit (ECU) Performance RAM Error

Live data Qty (0)

● Engine Control Module (ECM)



● Engine Control Module (ECM)



Version Information

DTC Qty (2)

P0455-00	Evaporative Emission (EVAP) System Large Leak Detected
P2119-00	Throttle Closed Position Performance

Live data Qty (0)

● Theft Deterrent Module (TDM)



Version Information

DTC Qty (3)

B1000-36	Electronic Control Unit (ECU) Performance EEPROM Failure
B3055-00	No Transponder Modulation or No Transponder
B3935-57	Transponder Authentication Error

Live data Qty (0)