

OEM schematic neglected to show this connection. Added for clarity. Removed this pin from PCM to add in electric fan control.

