


Available Carts: 2022-05-04 01:30:06 

## Shopping Cart

Part


Price


Quantity

Total


 No Vehicle Specified

### Steering : Tie Rod End

GM GENUINE 19178561	D		\$43.79	<input type="text" value="2"/>	\$87.58
---------------------	---	--	---------	--------------------------------	---------

GM GENUINE 15254061	D		\$70.79	<input type="text" value="2"/>	\$141.58
---------------------	---	--	---------	--------------------------------	----------

### Suspension : Coil Spring

GM GENUINE 20842473	C		\$70.99	<input type="text" value="2"/>	\$141.98
---------------------	---	--	---------	--------------------------------	----------

Coil Spring replacement requires a [Coil Spring Compressor](#).  
A [Ball Joint Separator / Pickle Fork](#) is also helpful for this repair.


GM GENUINE 25783732	A		\$51.79	<input type="text" value="1"/>	\$51.79
---------------------	---	--	---------	--------------------------------	---------

Coil Spring replacement requires a [Coil Spring Compressor](#).  
A [Ball Joint Separator / Pickle Fork](#) is also helpful for this repair.

### Suspension : Shock Absorber


ACDELCO 19420491 {Click Info Button for Alternate/OEM Part Numbers} GM Original Equipment	C		\$267.89	<input type="text" value="2"/>	\$535.78
---	---	--	----------	--------------------------------	----------

Do you need a [Shock Absorber Nut Tool](#) or [Ratcheting Wrench](#)?  
You should never use an impact wrench, pliers or vice grip to install the external Shock Absorber mounting nut, as this can damage the shock.

ACDELCO 5801093 {Click Info Button for Alternate/OEM Part Numbers} GM Original Equipment	C		\$261.99	<input type="text" value="2"/>	\$523.98
--	---	--	----------	--------------------------------	----------


Do you need a [Shock Absorber Nut Tool](#) or [Ratcheting Wrench](#)?  
You should never use an impact wrench, pliers or vice grip to install the external Shock Absorber mounting nut, as this can damage the shock.

### Suspension : Stabilizer Bar End Link / Bushing

GM GENUINE 25918049	D		\$16.42	<input type="text" value="2"/>	\$32.84
---------------------	---	--	---------	--------------------------------	---------

GM GENUINE 15257472	D		\$27.89	<input type="text" value="2"/>	\$55.78
---------------------	---	--	---------	--------------------------------	---------

### Suspension : Strut Mount
















GM GENUINE 25940743	D		\$99.79	<input type="text" value="2"/>	\$199.58
---------------------	---	--	---------	--------------------------------	----------

### Suspension : Strut Rod Lock Nut

GM GENUINE 15815519	C		\$6.03	<input type="text" value="2"/>	\$12.06
---------------------	---	--	--------	--------------------------------	---------

### Suspension : Control Arm

GM GENUINE 25812725 Includes Ball Joint	D		\$144.79	<input type="text" value="1"/>	\$144.79
---	---	--	----------	--------------------------------	----------

GM GENUINE 25812726 Includes Ball Joint	C		\$145.79	<input type="text" value="1"/>	\$145.79
GM GENUINE 20869201	D		\$145.79	<input type="text" value="1"/>	\$145.79
GM GENUINE 20869202 {22952194}	D		\$154.79	<input type="text" value="1"/>	\$154.79
GM GENUINE 22868629	D		\$43.79	<input type="text" value="2"/>	\$87.58
GM GENUINE 20917465	A D		\$35.79	<input type="text" value="2"/>	\$71.58
<b><u>Suspension : Coil Spring Seat / Insulator</u></b>					
GM GENUINE 84061243	D		\$14.40	<input type="text" value="2"/>	\$28.80
GM GENUINE 15840291	D		\$28.99	<input type="text" value="2"/>	\$57.98
GM GENUINE 20841899	A		\$4.25	<input type="text" value="2"/>	\$8.50
<b><u>Steering : Rack and Pinion Bellow</u></b>					
GM GENUINE 15254057	D		\$33.79	<input type="text" value="2"/>	\$67.58
<b><u>Suspension : Control Arm Anchor Bolt</u></b>					
GM GENUINE 15733533	D		\$6.08	<input type="text" value="2"/>	\$12.16
GM GENUINE 15733534	D		\$6.11	<input type="text" value="2"/>	\$12.22
<b><u>Suspension : Alignment Camber Plate</u></b>					
ACDELCO 45K5012 {19287859} Gold; Non-Greasable; Kit	A		\$24.79	<input type="text" value="2"/>	\$49.58
<b><u>Suspension : Leaf Spring Insulator</u></b>					
GM GENUINE 15251980	C		\$6.28	<input type="text" value="2"/>	\$12.56
GM GENUINE 15765071	A		\$5.93	<input type="text" value="2"/>	\$11.86
<b><u>Suspension : Alignment Guide Pin</u></b>					
ACDELCO 45K26008 {19145608} Gold; Priced Individually	E		\$3.19	<input type="text" value="4"/>	\$12.76
Selected <input type="text" value="\$3.19"/> {1}+ <input type="button" value="v"/>					

+ [Sold in packs of x](#). Price reflects cost of each individual item, not the pack.

---

**Suspension : Strut Mount Washer**

GM GENUINE 11548570

B



\$2.86

**\$5.72**

**\* Stocked in outlying warehouse--shipping delayed up to 8 business days**

---

Subtotal \$2,812.99