

Aug 02 2017 07:20:25-PM

VIN retrieved from vehicle

VIN: 3GYFK66N65G235719

1 Airbag Trouble Codes:

- B0104: CURRENT/HISTORY - Check report for description.

1 HVAC Trouble Codes:

- B0229: CURRENT/HISTORY - Check report for description.

2 Rear Climate Control Panel Trouble Codes:

- B3531: CURRENT/HISTORY - Air flow control #10 (rear) circuit malfunction
- B0429: CURRENT/HISTORY - Check report for description.

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.